


BONE YARD BOATS®

Saving Old Boats Since 1996

Issue 65: Fall 2014

SAILED THE MEDITERRANEAN, TO THE CARIBBEAN



1963 BUCHANAN 33' FAST CRUISER SLOOP

1963 BUCHANAN 33'. Owner says, "The boat was built in England in 1963 and sailed the Mediterranean, to the Caribbean, to Port Townsend, and all over the Inside Passage and around Vancouver Island. It is listed in the Lloyds Register under the name SEA SAUNTERER. It has oak ribs, Purple Heart post and horn timber, and Sapele planking. The deck is plywood with fiberglass and is in good condition. It is currently undergoing a restoration, but the owner can no longer do the work. It has had many new planks put on. There is a new purple heart horn timber partly shaped and the shaft holes bored. It needs a number of ribs replaced, and some lower planking. The interior was removed for the repair, so you could build it to suit your needs." (continued on page 8.)



FREE BOAT: 1969 TROJAN SEDAN 36' – Details on page 2.

RESTORATION OFF TO A GOOD START



1928 Wm ATKIN SHOAL-DRAFT CUSTOM KETCH 30'

1928 Wm ATKIN SHOAL-DRAFT KETCH 30'. Michael says, "Due to the death of a close friend of mine, this Atkin Ketch restoration project is currently for sale. When Rich obtained the boat, the interior had been completely disassembled in preparation for restoration. To many, Rich explained his vision of this boat again sailing on Lake Saint Clair for which it was designed. However, when his brother and I viewed the situation in a storage barn in the woods of the northeastern Lower Peninsula, the vision seemed a bit "lofty". (continued on page 9.)



1968 PACEMAKER 38' AFT CABIN w/ FLYBRIDGE – BLACK FALCON

1968 PACEMAKER 38'. Bone Yard Boats friend and wooden boat restorer Jim H. says, "Hi David, I got a call from a lady who has a mid 1960's 40' Pacemaker with twin 318's. The boat is on the hard in Port Dover, and she claims that it was blocked improperly and now is not restorable. You and I both know that is never true. This boat is as big as a house and would make an excellent floating cottage. I saw some fresh water intrusion on the top decks due to exposure, but the bottom looks like it is in reasonable shape." (continued on page 9.)